

82-A Series Power Cable Splice Kit

Instructions



Wire connector system for use with underground conductors.

1.0 Applications:


Designed for use in weather-exposed or direct-burial locations. For making inline (straight) splices on unshielded, synthetic insulated cables rated up to a maximum of 5kV and for multiple conductor cables rated up to a maximum of 1kV. UL Listed for direct burial and submerged applications up to 600 volts and 90°C. For use with UL Listed connectors only. These kits will accommodate the following connectors and conductor sizes:

Table A

Kit No.	Conductor Size	Connector O.D.	Cable O.D.	Sheath Opening (L)	(A)	(B)		
82-A1	#2 AWG (max.)	13/32" (maximum)	5/8" (maximum)	4 1/2" (maximum)	1/2 connector length	1/4" 1		
82-A2	#2 AWG (min.) #3/0 (max.)	5/8" (maximum)	1" (maximum)	6" (maximum)	1/2 connector length	1/2"		
82-A3	#3/0 (min.) 400 kcmil (max.)	1" (maximum)	1 9/16" (maximum)	9" (maximum)	1/2 connector length	1/2" 1		

2.0 Kit Contents:


Mold Body	A
Pouring Spouts	B
Scotch [™] 23 Electrical Tape	C
3M TM Scotchcast TM No. 4 Resin	



3.0 Prepare Cable:


3.1 **For 1000 volt:** Thoroughly scrape all wax and dirt 5" back from each cable end. Prepare cable ends exactly as shown. See Table A for proper sizing and dimensions.

Sheath CutbackA



3.2 For 5 kV maximum: Thoroughly scrape all wax and dirt 5" back from each cable end. Prepare cable ends exactly as shown. Do not cut insulation while removing outer sheath. See Table A for proper sizing and dimensions.

Bare Conductor	A
Insulation Pencil	B
Maximum Sheath Opening	L




4.0 Connection

- 4.1 Make connections according to instructions for connector being used. The mold will accept:a) Crimped type connectors and b) Split solder sleeve connectors.
- 4.2 **Multi-conductor Cables.** Stagger individual connectors (provide lateral spacing of 1/2" between ends of connectors) and insulate connector with Scotch[™] 23 Electrical Tape. Sheath opening should not exceed dimension "L" in Table A.

Note: Connectors not provided with kit.


4.3 **Tape Over Connector Area.** Apply one layer, half-lapped, Scotch 23 Electrical Tape over connector area only. Do not wrap tape onto the pencilled area.



5.0 Install Mold Body


5.1 Trim mold ends with knife to fit cable slightly loose. Hold mold halves in place, centered over splice. Snap mold halves together firmly. Check to see that both seams are carefully snapped together. Tape ends of mold body around cable to seal. Use supplied Scotch 23 Electrical Tape.

IMPORTANT: Stretch tape to 3/4 original width.



6.0 Pour Splice

- 6.1 Put pouring spouts in holes.
- 6.2 Position splice level. Mix resin thoroughly per instructions on resin package. Pour resin immediately after mixing. Fill only through one spout until both spouts are completely filled. When resin has solidified and cooled, splice may be put into service. Clip off spouts, if desired.





3M, Scotch, Scotchlok and Scotchcast are trademarks of 3M.

IMPORTANT NOTICE

Before using this product, you must evaluate it and determine if it is suitable for your intended application. You assume all risks and liability associated with such use.

Warranty; Limited Remedy;Limited Liability. This product will be free from defects in material and manufacture as of the date of purchase. 3M MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. If this product is defective within the warranty period stated above, your exclusive remedy shall be, at 3M's option, to replace or repair the 3M product or refund the purchase price of the 3M product. Except where prohibited by law, 3M will not be liable for any loss or damage arising from this 3M product, whether direct, indirect, special, incidental or consequential regardless of the legal theory asserted.



Electrical Products Division 6801 River Place Blvd. Austin, TX 78726-9000 800/245-3573 http://www.3M.com/elpd

