

Table 7.1—242E Parts List

Item	Description	Part No.	Per Unit
	Blue, Scanner, High Temp.	9A-BDP-S-1-BL-S-6	
	Blue Scanner, Low Temp.	9A-BDP-S-1-BL-L-6	
	Black, Scanner, High Temp.	9A-BDP-S-1-BK-S-6	
	Black Scanner, Low Temp	9A-BDP-S-1-BK-L-6	
	Blue, Integrator, High Temp.	9A-BDP-I-1-BL-S-6	
	Blue Integrator, Low Temp.	9A-BDP-I-1-BL-L-6	
	Black, Integrator, High Temp.	9A-BDP-I-1-BK-S-6	
	Black Integrator, Low Temp.	9A-BDP-I-1-BK-L-6	
	Blue, Universal, High Temp. ****	9A-BDP-U-1-BL-S-6	
	Blue Universal, Low Temp. ****	9A-BDP-U-1-BL-L-6	
	Black, Universal, High Temp. ****	9A-BDP-U-1-BK-S-6	
	Black Universal, Low Temp. ****	9A-BDP-U-1-BK-L-6	
	High Temp = +20° to +120° F (-7° to 48°C); Low Temp = -40° to +90° F (-40° to 32° C)		
29*	Disposable Pen, 2nd from Chart, 6 per pkg		A/R
	Red, Scanner, High Temp.	9A-BDP-S-2-RD-S-6	
	Red Scanner, Low Temp.	9A-BDP-S-2-RD-L-6	
	Red, Integrator, High Temp.	9A-BDP-I-2-RD-S-6	
	Red Integrator, Low Temp	9A-BDP-I-2-RD-L-6	
	Red, Universal, High Temp. ***	9A-BDP-U-2-RD-S-6	
	Red Universal, Low Temp ***	9A-BDP-U-2-RD-L-6	
	High Temp = +20° to +120° F (-7° to 48°C); Low Temp = -40° to +90° F (-40° to +32°C)		
30*	Disposable Pen, 3rd from Chart, 6 per pkg (Not shown)		A/R
	Green, Scanner, High Temp.	9A-BDP-S-3-GN-S-6	
	Green Scanner, Low Temp.	9A-BDP-S-3-GN-L-6	
	Green, Integrator, High Temp.	9A-BDP-I-3-GN-S-6	
	Green Integrator, Low Temp.	9A-BDP-I-3-GN-L-6	
	Green, Universal, High Temp. ****	9A-BDP-U-3-GN-S-6	
	Green Universal, Low Temp ****	9A-BDP-U-3-GN-L-6	
	High Temp = +20° to +120° F (-7° to 48°C); Low Temp = -40° to +90° F (-40° to 32°C)		
31*	Disposable Pen, 3rd from Chart, 6 per pkg (Not shown)		A/R
	Purple, Universal, High Temp. ****	9A-BDP-U-4-PL-S-6	