



US2:2020379-701

Kit, 2-cell, filament 2-cell filament detector repair kit for MAXUM Edition II

List Price	Show prices
<b>Customer Price</b>	Show prices
Service & Support (Manuals, Certificates, FAQs...)	<a href="#">Download</a>



Image similar

**Product**

Article Number (Market Facing Number)	US2:2020379-701
Product Description	Kit, 2-cell, filament 2-cell filament detector repair kit for MAXUM Edition II
Product family	Ordering Data Overview
Product Lifecycle (PLM)	PM300:Active Product

**Price data**

Region Specific PriceGroup / Headquarter Price Group	824 / 824
List Price	Show prices
Customer Price	Show prices
Surcharge for Raw Materials	None
Metal Factor	None

**Delivery information**

Export Control Regulations	AL : N / ECCN : EAR99I
Standard lead time ex-works	1 Day/Days
Net Weight (kg)	0,019 Kg
Package size unit of measure	Not available
Quantity Unit	1 Piece
Packaging Quantity	1

**Additional Product Information**

EAN	Not available
UPC	Not available
Commodity Code	73181562
LKZ_FDB/ CatalogID	PA30AI-M
Product Group	4682
Group Code	R351
Country of origin	United States of America
Compliance with the substance restrictions according to RoHS directive	Since: 15.05.2017
Product class	B: return restricted, please contact your Siemens partner/contact
WEEE (2012/19/EU) Take-Back Obligation	No
REACH Art. 33 Duty to inform according to the current list of candidates	

**Classifications**

	Version	Classification
eClass	12	27-15-06-91
eClass	6	27-15-06-91
eClass	7.1	27-15-06-91
eClass	8	27-15-06-91
eClass	9	27-15-06-91
eClass	9.1	27-15-06-91